

## Environmental impacts

This bulletin aims to present very poor environmental management practices supported by photographic material.

EHSEC hopes that this material is used for reference in training sessions or for benchmarking purposes.

EHSEC also urges all members to contribute with relevant material as long as the material:

- Was legally obtained
- The photograph does not reveal the identity of workers by showing their faces.
- The photograph does not reveal the identity of the company depicted.
- The photograph does not reveal the identity of any brand name.
- Is not protected by copyright issues

All rights for the pictures contained in this bulletin are protected.



**Maintenance Department “leftovers”: A substandard kiosk built to house maintenance fluids, out-of-order equipment and materials; the environmental impacts identified include soil contamination with toxic fluids (maintenance chemicals mainly acids and lubricants).**



**In most cases poorly maintained equipment burden the soil with oil leaks.**



**Lack of maintenance creating fugitive emissions point that creates dust pollution throughout a plasters production plant; the results are obvious throughout the facility.**



**Maintenance debris after a construction work freely dumped in an open pit for subsequent burning; apart from the direct pollution to the soil, there is perspective pollution to the soil after a rainfall as well as after the uncontrolled waste burning.**



**Good practice: Maintenance chemicals stored in secondary containment**